

# **Inspection report**

Inspection damage 300 TPD six stage flash evaporator on the  
Ms Love boat 2



Client: Love boat company

.....

Technical Superintendent Sr.

.....

.....

USA .....

Author: J. van Duijn Cobra Consultancy

Report nr. 1-2416

Date: 03/04 june 2025

Page: 1

Pages:17 incl. Attachment

## **Introduction:**

---

Cobra Consultancy Rechthuisstraat 19 2391 DB Hazerswoude dorp  
Tel.: (+31)172 586002 / Fax.: (+31)847194990/ Internet: <http://www.cobraconsultancy.nl> / E-mail: [info@cobraconsultancy.nl](mailto:info@cobraconsultancy.nl)  
KvK Leiden 28066857 / BTW NL06.74.88.341.B.01

Iedere aansprakelijkheid van Cobra Consultancy, uit welke of terzake waarvan dan ook, is uitdrukkelijk beperkt tot maximaal het bedrag dat door Cobra Consultancy aan u in rekening is gebracht en of tot maximaal het bedrag dat in het desbetreffende geval uit hoofde van de aansprakelijkheidsverzekering door de verzekeraar wordt uitbetaald.

Mister ..... Technical Superintendent Sr. Love boat company has requested Cobra Consultancy to investigate a damaged 300 TPD six stages flash evaporator on the Ms. Love boat 1.

Damage on one of the evaporators occurred and the chief engineer of the Love boat Mr. ....send me some photos that showed me a typical example of erosion corrosion. During the 3<sup>th</sup> and 4<sup>th</sup> of June we investigated the total damage of the evaporator on board of the MS. Love boat. Unfortunately there were no technical drawings and material data of the evaporator at hand. The Chief engineer informed me that the material that was used constructing the evaporator, is a metal substance called Cupro nickel: also known as Cunifer.

After analyses in a laboratory of two little pieces of material, removed from the tube and the baffle box it came clear that the tubes as well as the baffle boxes are not made out of Cunifer or Cupro Nickel?

### History:

The 300 TPD six stages evaporator was installed around twenty years ago on the Love boat 1 (around 89) which is now called Love boat 1. In 2003 the tubes were cleaned and the gasket was probably not replaced for a new one.

### Inspection

The first impression of the evaporator was the enormous damage of the tube sheets especially the tube sheets SB2 and BB2 in the middle of the evaporator.

Tube sheet SB2 (a part of the measuring holes)

Left	Middle	Right
9mm	4,7mm	9mm
11,2mm	2,9mm	9,1mm
13,1mm	14,1mm	10mm
9,1mm	11,6mm	11mm
8,9mm	7,1mm	
6,1mm	3,9mm	13,1mm
5,9mm		
2,1mm		

Tube sheet BB2 (a part of the measuring holes)

Left	Middle	Right
6,5mm		1,5mm
8mm		3mm
11,5mm		2,1mm
9mm		3,0mm
		3,0mm

## Tube sheet SB1

Left	Middle	Right
4,1mm		
3,1mm		
3mm		
4,1mm		

## Tube sheet BB1

Left	Middle	Right
6,0mm		6.0mm
5mm		5,5mm
5,0mm		

Tube sheet SB3 and BB3 are not damaged by erosion

### Conclusion and progress

The First impression of the evaporator was the enormous damage of the tube sheets especially the tube sheets SB2 and BB2. The deepest measured hole in the middle of the tube sheet SB2 is 14,1 mm. The deepest hole on the left side of the tube sheet BB2 measured 11,5mm

The damage of the tube sheets and the tubes has started as a result of short circuits between the gaskets and the tube sheet.

After cleaning the tubes the gasket was probably not renewed, probably the surface under the gasket was not cleaned as a result of leakage between the gasket and the material.

But the biggest problem with this installation is the fact that the evaporator is not manufactured as stated from the material Cunifer. See material analyses in the appendix page. 16 &17. This made the evaporator much more sensitive to erosion of the material present here!

### Options

1. Repair through applying a paste substance of Copper epoxy called Devcon.

*This will be a temporary solution because the extremely erosion of the baffle boxes. It is also nearly impossible to create a total smooth surface of the tube sheet to seal the spacing entirely.*

*Inserts need to be placed because some tubes are worn out for over 50 % on the pipe plate by erosion*

2. Repair to bore out/ level off the tubes.

*The 6 baffle boxes and the tube sheets will be leveled on a boring machine.*

*But the tube sheets especially the middle tube sheet after reducing more than 10 mm.  
After recalculation the strengths will probably too low and not justify anymore.  
See the attachment 1 Option 2: No option*

*According to the texture of material (analysis: C687 ALBs 76 % Cu and 21 % Zn) it's well known that during time, it's become rigid and therefore cracks will appear whilst rolling the tubes.  
This kind of material is also absolutely not suitable for welding.*

- The best and most reliable solution is to renew the pipe plates and tubes in order to realize the original capacity of the evaporator. Within the pipe plates slotted grooves will need to be made which will put the gasket in place during these extreme circumstances.*

### Note

It's recommendable to perform checkups on a regular basis with these kind of evaporators. Endoscopy is a perfect way to investigate the condition of the baffle boxes, marine box and tube plates through a small interface made in the evaporator. Problems can be detected in a early stage and therefore you will be able to perform future damage control.

### Attachment:

1: 1 -4 offer company .....


5: Drawing Company .....example grooves in tube sheet

6: Material analyze baffle box

7: Material analyze tube



Evaporator Tube sheets




SB1 tube sheet 1 dirt in tubes



A lot of dirt in some tubes (close up)




Tubes damaged (close up)



Space between ruler and tube sheet 5 a 6 mm







Spaces between ruler and tube sheet



Maximum 4.1 mm tube sheet SB 1



Tube sheet SB 2



Space between tube sheet and ruler



Space 3 to 6 mm




13.1 mm deepest hole



Tubes sheet thickness reduce till 13 mm




Close up




Max. 14 mm material delivery



Baffle box SB 2



Erosion baffle box SB 2




Holes  $\Delta$  3 mm



Tube sheet SB 3 no material delivery



Baffle box SB3 little material delivery



In the middle reducing material (FWD) about 2 a 3 mm



FDW reducing material space 2 a 3 mm



BB3 no material delivery




Dirt in some of the tubes



Destruction two tubes



Leakage tubes



Deepest hole 11.5 mm BB 2



Leakage



BB 1 deepest hole 6 mm



Dirt in tubes



Dirt in tubes



Leakage



FDW




Space between ruler and marine box 1.5 till 3 mm



Space between ruler and marine box FDW  $\Delta$  2mm



AFT marine box



Space between ruler and marine box AFT 3mm




Close up erosion



Space between  $\Delta$  2 mm



SB side evaporator




14,1 mm in the Middle


SB2

The deepest holes


left 13,1 mm



BB2 deepest hole 11,5mm



4,1 mm Tube sheet SB1 deepest hole left side




BB1 Tube sheet deepest hole 6mm


5,5 mm right side



Endoscopic photos




Part of tube removed by erosion



Dirt in tubes SB1



Tube sheet SB1




Tubes inside evaporator



View under tubes SB

**Repair:**



C:\Program Files\Autodesk\Inventor 2009\Templates\Kapp\A3.offerte.dwg

**Example:**

Slotted grooves will need to be made which will put the gasket in place during these extreme circumstances!

## Attachment

**Certificate of Verification**

XL3t-35084

Reading No 314

Mode ALLOY

Time 2009-06-05 12:13

Duration 147.62

Sequence Final

Alloy1 No Match : \*4.15

Alloy2 No Match : \*4.79

Baffle box MS Prinsendam

Alloy % ± Error

Sb 0.086 ± 0.015

Sn 7.444 ± 0.055

Pd 0.000 ± 0.003

Baffle box

Piece for analyze

Ag 0.224 ± 0.161

Ru 0.000 ± 0.002

Mo 0.002 ± 0.001

Nb 0.004 ± 0.002

Zr 0.000 ± 0.003

Bi 0.006 ± 0.008

Pb 3.359 ± 0.035

Se 0.000 ± 0.003

W 0.000 ± 0.019

Zn 2.070 ± 0.026

Cu 85.932 ± 0.309

Ni 0.693 ± 0.015

Co 0.001 ± 0.004

Fe 0.036 ± 0.007

Mn 0.000 ± 0.006

Cr 0.000 ± 0.005

V 0.035 ± 0.005

Ti 0.081 ± 0.004

Al 0.000 ± 0.361

P 0.000 ± 0.026

Si 0.025 ± 0.052

Mg 0.000 ± 0.001



## Attachment



**cobra CONSULTANCY**  
Inspection • Water • Corrosion

Certificate of Verification  
XL3t-35084  
Reading No 316  
Mode ALLOY  
Time 2009-06-05 12:20

Duration 61.38  
Sequence Final  
Alloy1 C687AlBs : 0.32  
Alloy2 No Match : \*2.19  
Flags

SAMPLE:

Tubes evaporator MS Prinsendam  
Piece for analyze

Alloy % ± Error

Sb 0.007 ± 0.013

Sn 0.023 ± 0.009

Pd 0.001 ± 0.004

Ag 0.135 ± 0.096

Ru 0.000 ± 0.002

Mo 0.008 ± 0.001

Nb 0.062 ± 0.003

Zr 0.000 ± 0.002

Bi 0.002 ± 0.002

Pb 0.020 ± 0.004

Se 0.000 ± 0.002

W 0.000 ± 0.054

Zn 21.105 ± 0.186

Cu 76.398 ± 0.618

Ni 0.067 ± 0.007

Co 0.000 ± 0.004

Fe 0.198 ± 0.008

Mn 0.012 ± 0.005

Cr 0.004 ± 0.007

V 0.000 ± 0.010

Ti 0.047 ± 0.016

Al 1.686 ± 0.787

P 0.000 ± 0.051

Si 0.223 ± 0.100Mg 0.001 ± 0.001

